



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D2596**Job Sheet 190977****Part No:** D2596**Job Qty:** 12 ea**Part Name:** Web, 205 Skidtube**Part Weight:** 0 lbs**Status:** New**Priority:** Medium**Job Created:** 2/20/19**Job Tracking No:****Due Date:** 3/8/19**Created By:** Jesse White**Type:** Stock**Description:** SIOP

Note: DWG REV D IPP: D 99.02.02 Changed QA to QC, Added Step 6 and Cost DM IPP Rev:E 07-07-09
Incorporated DEO 9183 JLM

Ship Via:**Bill of Materials****Job Routing**

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	12 Ea	3/8/19	3/8/19	0.00	0.00	Start Up Skid tubes		TF
100	Skid tubes	12 pcs	3/8/19	3/8/19	0.00	6.38	Skid tubes		TF
110	HandFinish	12 pcs	3/8/19	3/8/19	0.00	3.15	HandFinish1		DR 19/02/26
120	QC	12 pcs	3/8/19	3/8/19	0.00	0.00	QC5		BE
130	Packaging	12 pcs	3/8/19	3/8/19	0.00	0.00	Packaging3		TF
140	QC21-SA	12 Ea	3/8/19	3/8/19	0.00	0.00	QC21		DAS MAR 06 2019

Part Op 100 - 1- Cut D2500-3-100 to length: 99.5" 2- Use Jig DT8093 to drill pilot holes #30 3- Open to 0.630" diameter as per
Descriptions: Dwg D2596 4- Deburr

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2500-3-100	Ext'n -I' Beam Web 4"	12 pcs (1 ea)	90-Start up Operation	5083738

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	D2500-3-100	12	17	0

Part Specifications

Specifications could not be found.

Plex 2/20/19 11:45 AM dart.white.jesse

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QS1042)	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
FAULT CATEGORY ☐ ter ☐ effect ☐ r Instructions ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread					

Dart Aerospace Ltd.
 1270 Aberdeen Street
 Hawkesbury, ON K6A 1K7
 CANADA
 TEL.: 613 632-5200
 Email: sales@dartaero.com
 www.dartaerospace.com



Container No: S155807



Part: D2596

Job No: 190977

Serial No/Batch: S155807

Revision:

Inspector:


Exp Date:

Instructions: Various STC's

Date: 02/22/19

DART**RELEASED**
07 DEC 28

DESIGN <i>PH</i>	DRAWN BY <i>PH</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2596	REV. D SHEET 1 OF 1
DATE 07.04.17	TITLE 205 WEB		SCALE 1:20
A	96.09.16	NEW ISSUE	
B	97.07.23	Ø0.63 HOLE WAS Ø0.56	
C	98.09.14	INCORPORATED DEO 9097	
D	07.04.17	INCORPORATED DEO 9183	

**D2596 WEB**

- 1) MATERIAL: MAKE FROM D2500-3-100 EXTRUSION
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) DEBURR SHARP EDGES 0.010 TO 0.020

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor		
			QC / QA Coordinator		
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					